

Date	No:	Issue	Responsibility	Update May 2019
Dec 2014	AP93	Unregistered FP from C330 to C3311 needs registering. Clerk to find out procedure.	MR	<p>Ref: 3549839</p> <p>7.9.16 JM reported that evidence forms have been sent in to SCC Map officer manager – she will chase progress.</p> <p>2.11.16 Letter rec'd from Alexandra Maher, Definitive Map Officer to say claim will be prioritised at Nov. Meeting. Forms have been sent to landowner but no response as yet.</p> <p>11.1.17 No further progress reported.</p> <p>1.3.17 Still awaiting response from Definitive Map officer – this could take some time.</p> <p>17.1.19 Email sent asking for an update on progress – claims ref. CPM876. Later, reply from Mary George, Senior Definitive Map Officer saying that this case had been assigned a medium priority (of which we had been informed), it should normally take between 2 – 5 yrs to process but there are still 23 cases ahead of this one at the moment.</p>
June 2016	AP115	Silt has built up at Church Road end of C324 as in previous year	MR	<p>9.8.18 Flooding & blocked drains reported. Ref. 218757</p> <p>26.8.18 Further flooding reported Ref. 220130</p> <p>23.11.18 Phoned for update – spoke to Steve who will get back to us.</p> <p>4.1.19 Chased Highways – Nial said silt was responsibility of Dist Council and had been cleared last Sept – blocked drains were on the list to be inspected by Community warden. Clerk stressed this is an on-going problem which needed constant monitoring – a new request for an update on progress has been ordered.</p> <p>9.1.19 Co Cllr Robin Vickery to arrange meeting with Paul Gant, SCC Highways Mgr to view the problem.</p> <p>6.3.19 Robin Vickery will chase up meeting with Paul Gant.</p> <p>3.5.19 Works have been ordered to clear silt etc and this s/be done within 20 working days of 15th April (i.e. end of May).</p>

Date	No:	Issue	Responsibility	Update May 2019
Oct 2017	AP131	Water constantly trickling down FP no. 7 making it hazardous. GR 217479	MH	<p>3.8.18 Spoke to Chloe at SCC Highways – they will re-open the case, ref. 183593</p> <p>20.9.18 Highways have replied to say this is indeed caused by an underground spring which starts in an adjacent garden. The landlord is aware and the matter is being investigated.</p> <p>26.9.18 John Frith of Frith Blake Consulting Ltd phoned to say he is investigating the underground spring, there appears to be a blocked culvert. This requires a survey, then the owners (thought to be SCC Highways) will be asked to fix it.</p> <p>1.11.18 update – survey has been done, FBC trying (unsuccessfully) to contact SCC to discuss.</p> <p>23.11.18 Phoned Highways for update – above noted. Request sent to CDS for report.</p> <p>4.1.19 Chased Highways for progress – Community warden has been asked to follow this up.</p> <p>8.1.19 Update from Highways – no further progress</p> <p>21.1.19 Phoned John Frith for update</p> <p>4.2.19 Spoke to John Frith – he will chase Suffolk Flood & Drainage team for an update on ownership/responsibility of broken pipe & email details.</p> <p>4.3.19 Chased for update.</p> <p>3.5.19 Phoned John Frith again & left message asking for update. Also phoned Highways who have no further update.</p>
Feb 2018	AP135	Continuation of AP123, AP127, AP129&130 Ongoing problems with FP's 1, 3 & 20 (see above refs)	MH	<p>4.7.18 FP's 1 & 20 now much improved, FP20 has been successfully re-routed and new wooden bridges in place. Highways closed off old route when they put in the bridges – notice to be issued in next edition of FLN. FP3 still impassable due to boggy patch midway – clerk to contact Eliz Mansfield.</p> <p>16.7.18 Spoke to Mrs Mansfield, she will investigate FP3 and talk to farm manager – later, problem appears to be a broken</p>

Date	No:	Issue	Responsibility	Update May 2019
				<p>drain which they must fix and this is scheduled for October.</p> <p>5.9.18 Mrs Mansfield reported that FP's 1 & 20 are now fine but drainage of FP3 more complicated and will need careful planning and work schedule – she will keep us posted.</p> <p>7.9.18 Reports at PC meeting saying electric fence still too close to path on FP1 and that rough patches still exist on FP's 1 & 20 – this has been relayed to owners for investigation.</p> <p>30.10.18 Update from Elizabeth M saying SCC Highways has approved positioning of electric fences and they have rec'd no complaints about surface. Repairs to FP3 not yet commenced.</p> <p>4.11.18 Update from Debbie Adams – she has had no recent complaints about FP's 1 or 20 but will visit soon to check condition of these. She will also inspect FP3 as it has been virtually unusable all year due to broken drain.</p> <p>8.1.19 Extremely soggy patch reported halfway along FP1 to the north of R.Fynn making footpath virtually impassable.</p> <p>9.1.19 Clerk is awaiting a call back from Debbie Adams to discuss condition of FP's 1 & 3. Robin Vickery will also contact her to discuss way forward on getting these remedied.</p> <p>26.2.19 Left message for Debbie Adams to call back but she is on leave until 6th March.</p> <p>26.2.19 Emailed Eliz Mansfield for update.</p> <p>27.2.19 Reply saying she is also awaiting call from Debbie to discuss what can be done as she agrees this needs sorting out.</p> <p>7.5.19 Email rec'd from Eliz Mansfield with progress made on FP1.</p>
Jan	AP141	FP sign (FP7 near top of Church Lane) has been knocked over and is unsafe	MH	<p>6.2.19 Clerk to report</p> <p>11.2.19 Reported ref: 233452</p> <p>13.2.19 Forwarded to PROW ref: 4678832</p> <p>3.5.19 Chased – it's on the list to be done when contractors</p>

Date	No:	Issue	Responsibility	Update May 2019
				next in the area
Jan	AP142	Parking problems in Church Lane – vehicles churning up grass verges and causing obstruction to passing traffic	MH	<p>9.1.19 Discussed at PC meeting report, clerk to contact Flagship Housing.</p> <p>15.2.19 Reply received saying the housing manager will be consulted and possible action discussed.</p> <p>6.3.19 Flagship has obtained a quote for removing hedge & creating more parking space, they will contact occupants.</p> <p>30.3.19 Hedge has been removed and extra parking space made by putting down hardcore but it looks unfinished.</p>
March	AP143	Query to Highways –will GREEN grit bins still get refilled when necessary?	MH	<p>12.3.19 Ref: 236103</p> <p>21.3.19 Reply rec'd with official list of grit bins which will be refilled</p>