

Date	No:	Issue	Responsibility	Update March 2023
Dec 2014	AP93	Unregistered FP from C330 to C3311 needs registering. Clerk to find out procedure.	MH	<p>2.12.22 Notification rec'd from David Last that hearing to decide our application will be held at Endeavour House on 15th Dec 2022 at 10am. JM will speak at the meeting.</p> <p>8.11.22 Clerk requested assistance from Elaine Bryce to give her support on our behalf, to which she agreed.</p> <p>15.12.22 Hearing went in our favour and application to reinstate FP was upheld – this will probably go to an appeal.</p> <p>14.2.23 Modification Order rec'd together with copy of the order modifying Definitive Map and Statement for the area. Landowner has until 31.3.23 to appeal.</p>
Feb 2018	AP135	Ongoing problems with FP's 1, 3 & 20 (Continuation of AP123, AP127, AP129&130)	MH	<p>12.9.22 Overgrowth of vegetation on entire length of FP1- needs trimming back. Ref: 372367</p> <p>12.9.22 Two really boggy patches on the path itself going through the wooded area in the middle of FP1 probably caused by springs. Ref 367368</p> <p>14.9.22 It transpires, this part is actually in Tuddenham Parish but the following report was received from Highways: <i>'Thank you for your report, the natural springs along this path are problematic, as you know we have carried out extensive works in the past to try and address the issue, the route has been added to the Autumn cutting schedule with a request to pay particular attention to the side growth to create a greater width to allow people to bypass / deviate around the worst affected areas, we will continue to monitor.'</i></p>
Aug	AP155	Drains on C324 blocked by silt/leaves again	MH	<p>25.6.21 Elaine Bryce reported that since her intervention, drainage issue has been inspected by Highways Assessment Officer - drains will be cleared and jetted to the outfall within 20 working days and put on a higher cleansing schedule thereafter. They suggested ESC is asked to clear silt more often!</p> <p>29.10. 21 Traffic Manager David Chenery has suggested new signage to address the traffic priorities on C324 which would cost around £2000.</p> <p>3.11.21 TH has already spoken to David about the above and it seems that further talks are needed to result in a viable</p>

Date	No:	Issue	Responsibility	Update March 2023
				<p>solution. TH will circulate his proposals to the rest of the councillors.</p> <p>28.2.22 New proposals for signage still awaited.</p> <p>26.8.22 Elaine Bryce reminded we are still awaiting progress on traffic priority signage, regular cleansing etc.</p> <p>8.9.22 Elaine Bryce chased for news on above</p> <p>8.11.22 List of outstanding Highways problems sent to Elaine B.</p> <p>18.1.23 Elaine chased for update.</p> <p>10.2.23 Notification from Highways of drainage works to be carried out on C324 betw 21-24 Feb.</p> <p>13.2.23 Clerk phoned Highways to enquire details of above: they will clear silt and put camera down drains to track what's going on then assess situation from there.</p> <p>14.2.23 Email from EB saying she has spoken to Highways officer Paul West who will most likely fund priority signs for C324 at no cost to Playford PC – details to be confirmed later.</p>
May 2022	AP174	Church Lane still being used as a diversion when Butts Road is closed	Clerk	<p>21.3.22 Report by resident whose verge is being churned up by extra traffic while Butts Road is closed. Clerk to consult Co Cllr Elaine Bryce as this road should not be used as a diversion.</p> <p>26.8.22 Elaine has been reminded a solution is awaited on this.</p> <p>8.9.22 Elaine Bryce chased for news on above</p> <p>8.11.22 List of outstanding Highways problems sent to Elaine B.</p> <p>18.1.23 Elaine chased for update.</p> <p>4.2.23 Pic of large bus trying to squeeze down Church Lane sent to EB – this was later found to be the school bus.</p> <p>14.2.23 EB confirmed she will fund traffic signs in Church Lane to deter heavy traffic – quotation for £450 sent to EB to accompany her application to SCC for this.</p> <p>26.2.23 Confirmation that application has been submitted.</p>

Date	No:	Issue	Responsibility	Update March 2023
	AP176	Constant flow of water down Church Lane – underground spring?	Clerk	27.5.22 Reported - Ref: 362451 8.6.22 Reply from SCC saying this has been passed to Anglian Water in case it's a water leak – if not, there's little SCC can do. 20.1.23 Re-reported to Highways as recent icy weather has highlighted the problem of schoolchildren waiting for their bus at the bottom of the road plus real possibility of an accident if vehicles skid on the ice when they brake. Ref:386230 23.1.23 Reply rec'd saying this has been looked into and will "monitored regularly" but no action thought necessary at the moment
Feb 2023	AP177	Trip hazards on FP5: 4 x sawn-off ends of old railings protruding up in middle of FP	Clerk	22.2.23 Reported to Highways ROW ref: 391100
	AP178			0